

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Pascagoula Staging Area	Facility Location ID:	PG01
Assessment Date :	8/2/2010	Incident Name :	BP Spill
Physical Location :	2210 Petit Bois Street		
City, State :	Pascagoula, MS	County :	Jackson

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	
Additional Comments : Seven (7) roll offs located onsite- Duplicate samples of absorbent boom material were collected by START and CTEH contractors. No concerns regarding waste management practices were noted during the visit	